



1/10

FIG. 1




2/10

FIG. 2




3/10

FIG. 3




A diagram of a mechanical assembly. A curved base (24) supports a central block (27). The block is positioned on a horizontal surface (3). A dashed line (4) indicates a vertical axis through the center of the block. Two arrows, b_1 and b_2 , originate from the top of the block, pointing towards the right. A horizontal line (25) is shown below the base. A double-headed arrow at the bottom indicates a horizontal dimension, labeled C_1 and C_2 .

FIG. 6



6/10

FIG. 7



7/10

FIG. 8






FIG. 9




8/10

FIG. 10



9/10

FIG. 11



10/10

FIG. 12

